

UNIVERSITY OF PATRAS
ERASMUS+
29 February 2016


BEHAVIOUR OF THE TOWER DURING AND AFTER STABILIZATION WORKS

Lo Presti Diego

University of Pisa: d.lopresti@ing.unipi.it

G-183

OCT-11



LECTURE OUTLINE

- **Historical background**
- **Subsoil conditions**
- **Restoration works**
- **Closing remarks**

G-131


FIR-20



**Pisa,
Piazza dei Miracoli**


G-148

TOK-20




HISTORICAL BACKGROUND

CONSTRUCTION HISTORY




G-262

PISA-0



G-160

ATL-11



Cross section in the plane of maximum Inclination*

Weight 142 MN
Height of the centre of gravity 22.6 m
Overturning moment 327 MNm
Foundation pressure: Average ≈ 500 kPa
Maximum ≈ 980 kPa
Minimum ≈ 60 kPa


Catino (1838)

(*) Situation in year 1993

G-190

TOK-12

LEANING TOWER OF PISA – STRUCTURAL FEATURES




G-160

ATL-01

WHY CONCERN ABOUT STRUCTURAL SAFETY?


- High compressive stresses on external facing*
- External facing laying directly on infill masonry*
- Infill rubble; voids, cracks, inhomogeneities
- Almost no bond strength between infill and facing
- Stress concentration in bed joints of facing
- Weakening of tower shaft due to presence of stair case*

(*) Especially dangerous at level of first cornice




Leaning Tower of Pisa

History of the Tower's inclination




LEANING TOWER OF PISA

DEDUCED HISTORY OF INCLINATION



TILT OF PISA TOWER SINCE 1911




G-171

SZC-13

NET TILT OF TOWER FOUNDATION

(1938 through 1991)



G-148

TOK-16

PHENOMENON OF LEANING INSTABILITY


- Relevant for tall, heavy top, structures seated on compressible ground
- Soil structure interaction problem controlled by ground stiffness
- Evolving in self-driving process
- Column of wooden bricks built on a springy foam stratum [Hambly (1985)]

G-148

TOK-24

LEANING INSTABILITY PHENOMENON

Hambly (1985)



LOW, NON-LINEAR STIFFNESS


- TALL AND HEAVY TOP STRUCTURES SEATED ON COMPRESSIBLE SOIL
- SOIL-STRUCTURE INTERACTION PROBLEM
- ANALOGY WITH BUCKLING OF INELASTIC COLUMN

G-76

ISM-10

INVERTED PENDULUM: A SIMPLE MODEL OF LEANING INSTABILITY

Humbly (1985), Lancellotta (1993), Desideri & Viggiani (1994), Burland et al.(2013)



INVERTED PENDULUM: A SIMPLE MODEL OF LEANING INSTABILITY

Humbly (1985), Lancellotta (1993), Desideri & Viggiani (1994), Burland et al.(2013)

$$\begin{Bmatrix} \rho \\ \alpha \end{Bmatrix} = \begin{bmatrix} \frac{1}{k_p} & 0 \\ 0 & \frac{1}{k_\alpha} \end{bmatrix} \begin{Bmatrix} W \\ M \end{Bmatrix}$$

$$k_p = \frac{ED}{1-\nu^2} ; k_\alpha = \frac{ED^3}{6(1-\nu^2)}$$

- Circular plate on elastic half-space
- Vertical Load (W) and Overturning Moment (M_O)
- Settlement (s) and Rotation (α)
- Resisting Moment (M_R)
- Safety Factor (FS=M_R/M_O)


G-262

PISA-0

G-262

PISA-0

LEANING INSTABILITY: SOIL STRUCTURE INTERACTION IDEALIZATION



M → MODEL OF SOIL RESTRAINT:


a		Linear or non linear elastic spring
b		Linear or non linear elasto-plastic spring
c		Viscoplastic Maxwell model unlimited creep under
d		Viscoplastic standard solid limited creep

G-221

MIA-0

LEANING TOWER OF PISA STABILITY OF EQUILIBRIUM

Pepe (1995)
Lancellotta and Pepe (1998)




G-221

MIA-0

G-221

MIA-0


SUBSOIL CONDITIONS



G-148

TOK-18

SUBSOIL PROFILE AND SOIL PROPERTIES




G-204

DUB-03

SETTLEMENT AND HEAVE OF SURFACE OF UPPER PISA CLAY


Leonards (1979)



A-112

MAD-7


RESULTS OF SEISMIC CONE PENETRATION TESTS



G-148

TOK-02


GROUND WATER BENEATH PIAZZA DEI MIRACOLI



G-262

PISA-01


PIAZZA DEI MIRACOLI - ELEVATION +3.5 m m.s.l.



G-259

PISA-02


PERCHED GROUND WATER TABLE IN HORIZON "A" IN PROXIMITY OF PISA TOWER



G-107


SP-08

EFFECT OF GWL OSCILLATIONS WITHIN HORIZON A ON THE TOWER MOVEMENTS



G-262

PISA-04



RESTORATION WORKS (1990 to 2001)

G-171

SZC-19

THREATS TO THE TOWER INTEGRITY

- ❑ **Progressive growth of rotation at increasing rate, risk of falling over**
- ❑ **Risk of sudden masonry failure on the South side, between 1st and 2nd cornice**

G-171

SZC-14

INTERNATIONAL COMMITTEE FOR THE SAFEGUARD AND RESTORATION OF THE LEANING TOWER OF PISA

- ❑ **Appointed by Italian Prime Minister in May 1990**
- ❑ **A fourteen-member multidisciplinary body including experts of:**

- | | |
|---|--|
| <ul style="list-style-type: none">• Restoration• History of Arts• Archeology | <ul style="list-style-type: none">• Petrography and construction stones• Structural Engineering• Geotechnical Engineering |
|---|--|

G-190


TOK-07

TOWER SAFETY COMMITTEE'S LONG-STRUGGLED PRONOUNCEMENTS

- **Tower affected by instability of the equilibrium (leaning instability)**
[Hambly (1985), Lancellotta (1993), Desideri and Viggiani (1994)]
- **Simple rheological models suggested that Tower was in state of neutral equilibrium**
[Shanley (1946, 1947)]
- **According to physical and numerical modeling a further increase in inclination would have put the Tower at risk of collapse**
[Edmunds (1993), Pepe (1995), Viggiani (2002), Potts and Burland (2000)]
- **In the event of leaning instability, even a minor reduction in inclination should lead to a significant safety upgrade against collapse.**

G-190

TOK-08



GEOTECHNICAL MONITORING DURING STABILIZATION WORKS

■ AUTOMATIC, CONTINUOUS, REAL-TIME

- 8 Livellometers
- 7 Biaxial inclinometers
- 4 Monoaxial inclinometers
- 6 Telecoordinometers
- 23 Piezometers
- 9 Seismometers

■ TOPOGRAPHICAL SURVEYING, DISCONTINUOUS

- High precision levelling of 23 points near the Tower base*
- Geodetic measurements, horizontal movements of points V₁ and V₇
- High precision levelling of 24 points on Piazza*


(* All referred to the Deep Datum Point on the Piazza)

HIGHLY REDUNDANT, SHORT AND LONG TERM ORIENTED

BENCHMARKS FOR HIGH PRECISION LEVELLING OF TOWER AND OF PIAZZA DEI MIRACOLI

Benchmarks:

- Internal (101-109) } Tower
- External (1-15) } plinth
- Piazza dei Miracoli (1-24)



G-160

ATL-10

G-142

PAR-03


GEOTECHNICAL STABILIZATION (1)

- **Temporary, fully reversible (1993)**
 - ▶ 600⁽²⁾ kN Counterweight on North edge of plinth, safeguard against overturning
- **Final interventions aimed at long term stabilization (1998-2001)**
 - ▶ **Controlled ground extraction⁽³⁾ on North side**
 - ▶ **Structural connection of the Tower plinth to catino slab**
 - ▶ **Control of ground water table within Horizon A**

(1) Simultaneously, temporary and final masonry strengthening have been carried out

(2) In 1995 increased to 980 kN

(3) Called hereinafter Underexcavation




G-204

DUB-02

G-103

VAL-30

TILT OF PISA TOWER SINCE 1911




G-190

TOK-17

UNDEREXCAVATION TO CORRECT PISA TOWER INCLINATION


Terracina (1962)



- Reduction of contact pressure on South side
- The reduction of present inclination by max. 1° should be enough
- Simplest tool: removal of soil under North side by series of borings
- Desired reduction of Tower inclination can be achieved by regulating number, position and diameter of borings

Pisa-05

TOOL FOR GROUND EXTRACTION





- Internal casing rotating clockwise
- Auger rotating counter-clockwise

G-204

DUB-08

CABLE STAY STRUCTURE



G-103

VAL-41



G-103


VAL-42



G-131

FIR-07

HOLES FOR GROUND EXTRACTION PRELIMINARY UNDEREXCAVATION




G-204

DUB-04




HOLES FOR GROUND EXTRACTION FINAL UNDEREXCAVATION




G-204 DUB-04

ROTATION OF TOWER PLINTH DURING UNDEREXCAVATION




G-80 CL-82

SETTLEMENT OF TOWER PLINTH DURING UNDEREXCAVATION




G-80 CL-83



CONTROL OF PERCHED WATER TABLE ON NORTH SIDE




PERCHED GROUND WATER TABLE IN HORIZON "A"




ROTATION OF TOWER AFTER STABILIZATION WORKS



ROTATION OF TOWER PLINTH AFTER STABILIZATION WORKS




SETTLEMENTS OF TOWER PLINTH AFTER STABILIZATION WORKS



TOWER AND CATINO SETTLEMENTS ACROSS NORTH-SOUTH PLANE


February 2003 through April 2013




(*) Underexcavation completed in January of 2001

Leaning Tower of Pisa

Reduction of Tower's inclination




Before intervention



After intervention

Leaning Tower of Pisa

History of the Tower's inclination



G-102

NYp-13

THE GEOTECHNICAL TEAM

1 - M. JAMIOLKOWSKI

2 - J.B. BURLAND

3 - C. VIGGIANI



G-107

SP-07



HOW WILL THE TOWER BEHAVE IN FUTURE ?

TWO SCENARIOS CAN BE ENVISAGED:

PESSIMISTIC:

Tower will remain stable for a period of time, followed by resumption of rotation at a much reduced rate, granted at least 300 years of life.

OPTIMISTIC:


Leaning instability phenomenon has been stopped, continuing rotation will cease*.

(*) except for minor cyclic rotations induced by seasonal phenomena and ground water oscillations

G-142

PAR-10

LEANING TOWER OF PISA EXPECTED FUTURE BEHAVIOUR



**By Chumki Bhaban,
9 years old girl
from Bangladesh**

