




“Ο Σεισμός της Κεφαλονιάς”


καθ. Στέφανος Η. Δρίτσος

Πάτρα, 2015

1



2



3

ΘΕΣΗ	ΣΕΙΣΜΟΣ 03 ΦΕΒΡΟΥΑΡΙΟΥ 2014			26/01/2014
	ΑΠΟΣΤΑΣΗ Km	ΕΠΙΤΑΧΥΝΣΗ cm/sec ²	ΕΠΙΤΑΧΥΝΣΗ cm/sec ²	ΕΠΙΤΑΧΥΝΣΗ cm/sec ²
Αργοστόλι	17	264	232	383
Βασιλικάδες	26	57	53	95
Ληξούρι	12	667	601	510
Χαβριάτα	11	678	751	

4

1^{ος} και 2^{ος} ΣΕΙΣΜΟΣ

5



EPPO-ITSAC, 2014. Report on the Mw:6.0 Cephalonia earthquake of 3rd Feb 2014. Earthquake Planning and Protection Organisation-Institute of Engineering Seismology and Earthquake Engineering. <http://www.slideshare.net/itsak-eppo/20140203-kefaloniaeq-report-en> (downloaded 10/03/14). 6



EPPO-ITSAC, 2014. Report on the Mw:6.0 Cephalonia earthquake of 3rd Feb 2014. Earthquake Planning and Protection Organisation-Institute of Engineering Seismology and Earthquake Engineering. <http://www.slideshare.net/itsak-eppo/20140203-kefaloniaeq-report-en> (downloaded 10/03/14). 7



EPPO-ITSAC, 2014. Report on the Mw:6.0 Cephalonia earthquake of 3rd Feb 2014. Earthquake Planning and Protection Organisation-Institute of Engineering Seismology and Earthquake Engineering. <http://www.slideshare.net/itsak-eppo/20140203-kefaloniaeq-report-en> (downloaded 10/03/14). 8



Photograph – S. E. Dritsos

9



EPPO-ITSAC, 2014. Report on the Mw:6.0 Cephalonia earthquake of 3rd Feb 2014. Earthquake Planning and Protection Organisation-Institute of Engineering Seismology and Earthquake Engineering.
<http://www.slideshare.net/itsak-eppo/20140203-kefaloniaeq-report-en>
(downloaded 10/03/14).

10



EPPO-ITSAC, 2014. Report on the Mw:6.0 Cephalonia earthquake of 3rd Feb 2014. Earthquake Planning and Protection Organisation-Institute of Engineering Seismology and Earthquake Engineering.
<http://www.slideshare.net/itsak-eppo/20140203-kefaloniaeq-report-en>
(downloaded 10/03/14).

11



Livieratos, S., 2014. 1 building 300 years and 3 earthquakes. 20th Students Conference “Repair and Strengthening of Structures 2014”, University of Patras (in Greek).

12



IAS, 2014. Presentation of 2014 Kefalonia earthquakes damage assessment and statistics. Department of Earthquake Recovery, Argostoli, 6th March, 2014

13



IAS, 2014. Presentation of 2014 Kefalonia earthquakes damage assessment and statistics. Department of Earthquake Recovery, Argostoli, 6th March, 2014

14



15



16



17



18



19



Σ. Η. ΔΡΙΤΣΟΣ





25



26



27



28



29



30



31



32



33



34



35



36

